



5 LOBE ACTUATOR UPGRADE CONVERSION GUIDE

FOR SKI BOATS & TOW BOATS



FINDING YOUR (5) LOBE REPLACEMENT ACTUATOR & CONTROL BOX FOR DISCONTINUED (3) LOBE ACTUATORS

Follow these simple steps to find your 12 Volt Replacement Actuator and Control box

A

First you must locate the OEM Boat Builder of your non-working (3) lobe actuator.

B

Then you must locate the non-working (3) lobe actuator part number

C

Then locate the current control box being used in this same boat (This may still be working)

The replacement (5) lobe Lenco actuator and control box must be replaced at the same time in most cases! See the ORDERING INFO box to the right.

EXISTING (3) LOBE PRODUCT INFORMATION → ORDERING INFO NEW (5) LOBE PRODUCTS

OEM Boat Builder	Existing 3 Lobe Actuator	Existing OEM#	Existing 3 Lobe Control Box	New (5)Lobe Actuator	Quantity Needed	New (5) Lobe Control Box	Quantity Needed
Calabria	15117-001	20402-0013	30054-001	15057-001	2	30271-0125D	1
Epic	15117-001	20402-0013	30271-009	15057-001	1	30271-0095D	1
Fineline	15119-001	20740-0013	30203-001	15120-001	1	Use Existing 3L *	N/A
Malibu	15118-001	20791-0013	30047-004	15060-001	2	30271-0015D	1
Malibu	15118-001	20791-0013	30047-005	CALL LENCO MARINE CUSTOMER SERVICE AT (772) 288-2662			
Malibu	15118-001	20791-0013	30224-004	15060-001	2	30271-0015D	1
Malibu	15118-001	20791-0013	30226-001	15060-001	2	30271-0025D	1
Malibu	15118-001	20791-0013	30226-002	15060-001	2	30271-0035D	1
Malibu	15118-001	20791-0013	30271-001	15060-001	2	30271-0015D	1
Malibu	15118-001	20791-0013	30271-002	15060-001	2	30271-0025D	1
Malibu	15118-001	20791-0013	30271-003	15060-001	2	30271-0035D	1
MasterCraft	15119-001	20740-0013	30221-001	15120-001	1	30271-0065D	1
MasterCraft	N/A	20401-0013	30231-001	15055-001	2	30271-0045D	1
MasterCraft	15117-001	20402-0013	30232-001	15057-001	1	30271-0055D	1
MasterCraft	N/A	20401-0013	30271-004	15055-001	2	30271-0045D	1
MasterCraft	15117-001	20402-0013	30271-005	15057-001	1	30271-0055D	1
MasterCraft	15119-001	20740-0013	30271-006	15120-001	1	30271-0065D	1
MasterCraft	15117-001	20402-0013	30271-008	15057-001	2	30271-0085D	1
MasterCraft	15117-001	20402-0013	30271-009	15057-001	1	30271-0095D	1
MasterCraft	15117-001	20402-0013	30074-001	15057-001	1	Use Existing 3L *	N/A
MB Sports	15117-001	20402-0013	30275-001	15057-001	1	Use Existing 3L *	N/A
Skier's Choice	15121-001	20740-003	30203-001	15122-001	1	Use Existing 3L *	N/A
Tige	N/A	20400-0013	30243-001	15054-001	1	Use Existing 3L *	N/A
Tige	N/A	20740-0023	30243-002	15132-001	1	Use Existing 3L *	N/A

* Existing (3) lobe control box does not need to be replaced if it is in proper working order.